

ERO

ERO Resources Corp.
1842 Clarkson Street
Denver, CO 80218
(303) 830-1188
Fax: 830-1199

Sulphur Gulch Channel Improvements
T6S, R66W, Section 23,
UTM Coordinates: Zone 13; 4374000mN, 521600mE
Piney Creek Quadrangles,
Douglas County, Colorado

Figure 1
Site Location

Prepared for: UDFCD
File: 2020 Fig1.cdr
November 2002



ERO

ERO Resources Corp.
1842 Clarkson Street
Denver, CO 80218
(303) 830-1188
Fax: 830-1199

WETLANDS IMPACTS

WUS IMPACTS

File: E-2020-Improved.dwg



North

Scale: 1" = 50'

Figure 2
Wetland Impacts
Sheet Pile Drop Structure and Trail

Produced for: UDFCD
September, 2002



ERO Resources Corp.
1842 Clarkson Street
Denver, CO 80218
(303) 830-1188
Fax: 830-1199

WETLANDS IMPACTS

WUS IMPACTS

SAMPLE SITE

File: E-2020-Improved.dwg

North

Scale: 1" = 50'

Figure 3
Wetland Impacts
Drop Structure #1

Produced for: UDFCD
September, 2002



ERO

ERO Resources Corp.
1842 Clarkson Street
Denver, CO 80218
(303) 830-1188
Fax: 830-1199

WETLANDS IMPACTS

WUS IMPACTS

File: E-2020-Improved.dwg



North

Scale: 1" = 50'

Figure 4
Wetland Impacts
Drop Structure Nos. 2 & 3

Produced for: UDFCD
September, 2002



ERO

ERO Resources Corp.
1842 Clarkson Street
Denver, CO 80218
(303) 830-1188
Fax: 830-1199

WETLANDS IMPACTS

WUS IMPACTS

SAMPLE SITE

File: E-2020-Improved.dwg



North

Scale: 1" = 50'

Figure 5
Wetland Impacts
Drop Structure No. 4

Produced for: UDFCD
September, 2002